

John Citizen

**Order no.** :  
**Customer no.** :  
**Registration** : ABC123  
**Mileage** :  
**First registrat.** :  
**Fitter** : SCA  
**Telephone** :  
**Fax** :

Tel.(private) :

Tel.(business) :

FORD,Falcon [BA],Falcon / Fairmont (inc G & XR Series),Gasoline,4.0,182.0kw,10/2002 - 09/2004,H

**EECV R6 CAN**

1. Identification

18:25

1. Search result - Fault memory

18:26

EECV R6 CAN	4	
P0196 Engine oil temperature sensor	Outside specified range	
P1131 O2 sensor (bank 1, sensor 1)	mixture too lean	
P1132 O2 sensor (bank 1, sensor 1)	mixture too rich	
P1183 Engine oil temperature sensor	Malfunction	
4-sp. autom.transm. 1.2EEC	4	
P0196 Engine oil temperature sensor	Outside specified range	
P1131 O2 sensor (bank 1, sensor 1)	mixture too lean	
P1132 O2 sensor (bank 1, sensor 1)	mixture too rich	
P1183 Engine oil temperature sensor	Malfunction	
Centr.electronics CE 9.2.2	2	
B1982 Driver's door unlocking relay	Faulty	
B2891 Intermittent wipe switch	Faulty	

**4-sp. autom.transm. 1.2EEC****Centr.electronics CE 9.2.2**

Remarks: \_\_\_\_\_

Date

Signature